

Resistivity measurement

Measurement of resistivity can be performed with a 4 points method. For this measurement, it is important to distribute the current well over the width of the sample and to avoid contact resistance through copper tape or even copper plates. The voltage drop measurement should however be performed with small syringes to reduce the contact surface.

